



Atera® SIGNO


Skoda Oktavia Kombi 01/2005–
(o. Reiling/without rail/sans barres)



6



7




8

Atera SIGNO





Skoda
Oktavia Kombi 01/2005–
(ohne Reiling/without rail/sans barres de toit)

Part-No. : 044 096
Part-No. : 045 096



Part-No. : 044 096



Atera
MADE IN GERMANY


Atera GmbH
Im Herrach 1
D-88299 Leutkirch
Servicetelefon: 0180-50 000 89
(14 ct/Min. aus dem dt. Festnetz)
E-Mail: info@atera.de

Atera® SIGNO



Skoda Oktavia Kombi 01/2005–
(o. Reling/without rail/sans barres)

Atera® SIGNO

Skoda Oktavia Kombi 01/2005–
(o. Reling/without rail/sans barres)




INFO




1


2



3



4



5